


NPA 02/14

SUBJECT: AP0076 Engine Harness Connector Cover
February 10, 2014

Alliant Power is pleased to announce the release of **AP0076** Engine Harness Connector Cover for the below applications. Many service procedures, including injector replacement, require removal of the engine harness connector and the connector cover is often damaged in the process. Failing to replace a damaged connector cover will lead to a loose engine harness connection and ultimately a stranded vehicle. This connector cover is not available separately from the OEM and complete harness replacement is impractical and costly. **AP0076** provides a cost effective alternative to complete harness replacement.



AP PART NUMBER	YEAR RANGE	APPLICATION	OEM PART NUMBER
AP0076	2008–2010	F Series	N/A



New Product Announcement