SUBJECT: Pre-programmed Fuel Injection Control Module (FICM) for Navistar® Applications

Installing a pre-programmed FICM on an engine that does not have a current ECM calibration or matching reference number could cause catastrophic engine failure. If assistance is needed to verify ECM calibration status, please contact Technical Support at 800.735.9775.

When ordering a FICM, supplying the ECM reference number is required and can be located under the 'vehicle information' tab (image shown on right) in ServiceMaxx™. Specific ECM programming reference numbers can be found in the table below. Make sure the old FICM is plugged into the engine harness in order obtain the last 8 characters of the ECM reference number. If the ECM reference numbers is not displayed with the FICM plugged in, the FICM is damaged and will require a unprogrammed Alliant Power FICM AP65125.

For more information, refer to NPA 01/20.

AP Part Number	ECM Reference Number	Year Range	Engine Application
AP65126	ANZKHA03	2004-2006	I6
AP65127	ANZKLA03		
AP65128	ANZNHA04		
AP65129	ANZNHB00		
AP65130	ANZNLA04		
AP65136	ANZKHB00		
AP65131	AQZ0AT04	2006-2009	V6
AP65132	AHZ7AI07	2002-2006	V8
AP65133	ANZ7BJ05		
AP65134	ANZ7BJ07		
AP65135	ANZ7BJ10		
AP65125*	*Non-Programmed*	2004-2006	I6
	Non-Programmed	2002-2006	V8

R1 – Added AP65136 to the table
R2- Added AP65125 (non-programmed) to the table