



# TECHNICAL BULLETIN APTB-04/10

## Remanufactured 2003-2009 Ford 6.0L FICM Discussion

Date July 20, 2010

On July 8, 2010 Alliant Power released a line of remanufactured fuel injection control modules (FICMs) for 6.0L applications. These FICMs replaced the single FICM (AP65121) that Alliant Power previously offered. The new products come preprogrammed with the latest calibration available at the time of manufacture. Three part numbers are needed to address calibration changes relative to vehicle model year and application.

A pre-programmed FICM will allow on site repair to get a vehicle mobile again. Although these FICMs are pre-programmed, a FICM calibration that is inconsistent with the PCM calibration will cause a U0306 code. Code U0306 will not illuminate the malfunction indicator lamp (MIL) and should not affect vehicle operation or performance. Alliant Power recommends FICM/PCM recalibration if fault U0306 is present after installation of this product.

Year	Application	Description	OE Part Number	Alliant Power Part Number
<b>Reman 6.0L FICM</b>				
<b>F-Super Duty</b>				
2003	F-Super Duty	Reman 6.0L FICM	4C3Z12B599ABRM	AP65122
2004	F-Super Duty to 9-22-03	Reman 6.0L FICM	4C3Z12B599ABRM	AP65122
2004	F-Super Duty after 9-22-03	Reman 6.0L FICM	4C3Z12B599ABRM	AP65123
2005 - 2007	F-Super Duty	Reman 6.0L FICM	4C3Z12B599ABRM	AP65124
<b>Excursion</b>				
2003	Excursion	Reman 6.0L FICM	4C3Z12B599ABRM	AP65122
2004	Excursion to 9-22-03	Reman 6.0L FICM	4C3Z12B599ABRM	AP65122
2004 - 2005	Excursion 9-23-03 to 1-31-05	Reman 6.0L FICM	4C3Z12B599ABRM	AP65123
2005	Excursion after 1-31-05	Reman 6.0L FICM	4C3Z12B599ABRM	AP65124
<b>E-Series</b>				
2004 - 2009	E-Series	Reman 6.0L FICM	4C3Z12B599ABRM	AP65124

**Note:** The only difference between the three available FICMs is the calibration software. Improper application is acceptable if there is no other option. **Example:** An AP65122 can be installed on a 2007 F-Super Duty. To prevent runability issues and fault codes, it will require recalibration once installed.

*Note: For controlled formatted printing, this SPM is available as a \*.pdf file in the Authorized Dealers section of the DISnet website, .*

**Alliant Power Technical Support**  
 Phone: 866-283-1785  
 Fax: 800-237-5984