



SUBJECT: 7.3 L Engine Oil Temperature (EOT) Sensor Running Change

Ford has made a running design change and part number update to the 7.3 L Engine Oil Temperature (EOT) Sensor for model years 1994-2003. While the fit and function of the new sensor has not changed from the original sensor, the design change is distinguishable in the side-by-side photos below:



Old Style



New Style

Alliant Power will supply the new design sensors once existing stock is depleted. While the Alliant Power part number will not be changed, the table below includes OEM part numbers of both sensors for your cross-reference information.

Product description	AP part number	Ford part number	Motorcraft part number	International part number
7.3 L EOT Sensor (1994-2003)	AP63436	F5AZ12A648AB	DY961	1814320C1
		F31Z12A648A	DY1144	N/A

For more information visit

AlliantPower.com

Alliant Power Technical Support: 800.735.9775 | techsupport@AlliantPower.com