

## APTB 09/11 R1

# SUBJECT: AP0021 Injection Control Pressure (ICP) Connector Pigtail February 21, 2012



Alliant Power is implementing a running change to the **AP0021** Injection Control Pressure (ICP) Connector Pigtail Repair Kit. In an effort to provide a competitively priced product, the pieces accompanying the pigtail (heat shrink tubing, butt connectors, split loom and lubricant) will no longer be supplied.

We have also found that the **AP0021** pigtail is the appropriate connector for the repair of multiple 3-wire sensors offered by Alliant Power. The table below shows the sensor applications where the **AP0021** pigtail can be used.

AP0021 Applications	
Sensor Description	Sensor Part Number
Injection Control Pressure (ICP) Sensor	AP63407
	AP63418
	AP63460
Exhaust Back Pressure (EBP) Sensor	AP63408
	AP63403
	AP63423
	AP63429

R1-Added AP63460