

NPA 01/14

**SUBJECT: AP66992 & AP66995 Remanufactured
G2.9 BANG Injectors**


February 10, 2014

Alliant Power is pleased to offer the below Remanufactured G2.9 BANG Injectors at new reduced pricing. The process uses proven technologies and techniques acquired from the G2.8 remanufacturing process. Each unit is 100% flow tested to ensure product operation and durability.

Installation Information:

Replacement of G2.9 Injectors requires removal of the high–pressure oil rail. The injector inlet seals are incorporated on the oil rail and must be replaced prior to reinstalling. Alliant Power kit **AP0025** will provide the necessary seals and backup rings to reseal the rail properly.

All new products are backed with Alliant Power’s 13–month, unlimited mileage warranty, as well as Alliant Power’s technical support.



AP G2.9 Injectors are identified by the part number on the body.

AP PART NUMBER	OBSOLETE AP PART NUMBER	YEAR RANGE	APPLICATION	OEM PART NUMBER
AP66992	AP66892	2006	DT570: 285 HP to 330 HP	1848492C91
AP66995	AP66895	2006	HT570: 295 HP to 340 HP (HT)	1848495C91



New Product Announcement