


**APTB 06/13**

**SUBJECT: G2.8 Connector Dust Seal**

**October 22, 2013**

Occasionally, Alliant Power is forced to replace the electrical connector on G2.8 Injectors due to wear or damage. These new connectors are received by Alliant Power complete with the internal and external seals already installed. There is one visible difference with the new connectors that are used during the remanufacturing process, the internal dust seal.

The seal used by Alliant Power, in both the remanufacturing process as well as the **AP0002** G2.8 Injector Seal Kit, is orange in color. The seal supplied with new connectors is green in color.



While the color of the seal is different, the reliability of the seal is consistent and will not affect the performance of the injector or the integrity of the electrical connection. The two types of seals may also be intermixed on an engine with no influence on performance.

**Note:** *These Connectors are Currently not Sold Separately*



**Technical Bulletin**