

**SUBJECT: Stanadyne® Gasket Kits**

Due to a supply constraint issue of Stanadyne part number, 23190 Insulator Tube, a limited number of gasket kits will be supplied with qty 2 - 23190 being omitted. In the meantime, there will be a mix of the complete kits and kits missing the 23190 in Diesel Forward's inventory. Kits that are missing the 23190 are listed in the table below and will be identified with an orange dot (Figure 1).

As mentioned, the supply constraint will be limited and if you do receive a kit(s) with the missing insulator tubes and wish not to use them, Diesel Forward will allow the kit to be returned for full credit.

Gasket Kits Affected	Description
24369	DB & DC Pump Models
24372	DM Pump Models
33814	DB2 Ag/Industrial Models (including pumps with <i>Target</i> features)
33702	DB4 Pump Models (including pumps with <i>Target</i> features)

23190 ESO Isolator



Figure 1  
Orange Dot

