

SUBJECT: AP0198 Turbo Oil Supply Filter

Alliant Power's [AP0198 Turbo Retrofit Kit](#) for 2015-2016 Ford® 6.7L Power Stroke® includes a turbo oil supply filter. This filter must be installed into the bottom of the turbocharger pedestal prior to mounting turbo/pedestal assembly to the engine. Failure to install this filter may result in larger contaminants or particles entering the turbocharger's bearing system and causing catastrophic turbo failure.

The filter should be installed in the oil supply port of the pedestal as shown in Figure 1. Once installed, the filter should sit *flush* with surface of the pedestal. Failure to do so will cause damage to the filter when installing turbo/pedestal assembly onto engine.




Figure 1