

NPA 03/13

**SUBJECT: AP0069 High-Pressure Oil Rail Socket &
AP0070 High-Pressure Oil Rail Seal Kit**

May 6, 2013

Alliant Power is pleased to announce the release of **AP0069** High-Pressure Oil Rail Socket & **AP0070** High-Pressure Oil Rail Seal Kit. The seal kit provides a cost effective service solution, rather than complete replacement of the oil rail if a leak at an oil rail outlet fitting is found. AP0070 includes four seals to reseal one high-pressure oil rail.

AP0069 High-Pressure Oil Rail Socket is required in order to remove and install the oil rail outlet fittings on all G2.8 applications.

For further technical information regarding disassembly and assembly, refer to Alliant Power Technical Bulletin [APTB 02/13](#).



AP0070
High-Pressure Oil Rail Seal Kit



AP PART NUMBER	YEAR RANGE	APPLICATION	OEM PART NUMBER
AP0069	2003-2007	F Series, Excursion	N/A
	2004-2010	E Series	
	2006-2010	4.5 L LCF	
	2003-2007	VT365	
	2006	VT275	
	2007-2010	MaxxForce 5	
AP0070	2003-2007	F Series, Excursion	N/A
	2004-2010	E Series	
	2006-2010	4.5 L LCF	
	2003-2007	VT365	
	2006	VT275	
	2007-2010	MaxxForce 5	



New Product Announcement