

NPA 03/14
SUBJECT: AP66855, AP66857 & AP66858
G2.9 Injectors
April 22, 2014

Alliant Power is pleased to offer OEM G2.9 Injectors for the applications listed below.

Installation Information:

Replacement of G2.9 Injectors requires removal of the high–pressure oil rail. The injector inlet seals are incorporated on the oil rail and must be replaced prior to reinstalling. Alliant Power kit **AP0025** will provide the necessary seals and backup rings to reseal the rail properly.

All new products are backed with Alliant Power’s 13–month, unlimited mileage warranty, as well as Alliant Power’s technical support.



AP PART NUMBER	YEAR RANGE	APPLICATION	OEM PART NUMBER
AP66855	2010–2013	MaxxForce DT: 215 HP to 300 HP	1890055C92 1890056C2
AP66857	2010–2013	MaxxForce DT: 210 HP to 225 HP	1884057C92 1884058C2
AP66858	2010–2013	MaxxForce 9: 300 HP to 330 HP MaxxForce 10: 310 HP to 350 HP	1890057C92 1890058C2



New Product Announcement