

SUBJECT: Stanadyne® 24371 Gasket Kit

Due to a supply constraint issue of 26965 Stanadyne Transfer Pump Seal, which is used in Stanadyne 24371 Gasket Kit, the complete 24371 Gasket Kit will not be available until sometime in Q4 of 2023. Realizing this is a very important kit for the servicing of DB Style Mechanical Pumps, Stanadyne will be making a limited number of kits available without the qty 1 – 26965 Seal. The Stanadyne kits that are missing the 26965 Seal will be identified with a red dot next to the part number (Figure 1).

As a result of these incomplete kits, Alliant Power will be offering customers several options. A customer can purchase the Stanadyne 24371 Gasket Kit without the 26965 Seal but can order an aftermarket seal under the DIPACO part number D26965. For those customers who would rather purchase a complete 24371 kit, the DIPACO version is available for purchase as part number D24371.



Figure 1

26965 Seal