

**Service Kit For Sprinter  
2.7L (Van) Common  
Rail Injectors**

**DIPACO**  
**DIESEL**  
**PARTS**  
**U S A**

DIPACO now offers injector service kits for repairing Sprinter 2.7L (Van) common rail injectors.

Part number RTF25226 is for model years 2000 – 2003 with injector 0445110181.

Part number RTF25227 is for model years 2004 – 2006 with injector 0445110162.

The kits include commonly used internal and external parts for repairing 5 injectors.

Complete contents of the service kits can be found below.

**RTF25226**

<b>Part Number</b>	<b>Description</b>	<b>Qty</b>
RTF25013	O-Ring, Stator	5
RTF25049	Washer, Inlet Fitting	5
RTF25083	Injector Check Ball	5
RTF25225	Seal Ring Kit, Control Valve	5
DT270006	Nozzle Washer	5

**RTF25227**

<b>Part Number</b>	<b>Description</b>	<b>Qty</b>
RTF25013	O-Ring, Stator	5
RTF25049	Washer, Inlet fitting	5
RTF25225	Seal Ring Kit, Control Valve	5
RTF25228	Injector Check Ball, Ceramic	5
DT270006	Nozzle Washer	5

*An Employee Owned Company*

12693 Old Virginia Road  
Reno, NV 89521  
800.648.4720

**DIPACODTECH.com**