



Alliant Power Remanufactured Common Rail Injectors

Offering remanufactured common rail injectors for the 8.1L, 9.0L, 6.8L and 4.5L John Deere engine platforms.

- ▶ 18 part numbers provide extensive coverage
- ▶ Includes necessary components for installation and trim code (where applicable)
- ▶ 24-month, unlimited hours warranty
- ▶ Professional customer service and technical support

8.1L John Deere HPCR

| AP part number | Application | OEM part number |
|----------------|-------------|--|
| AP50900 | 8.1L | RE524361, RE518726, SE501936, 095000-5150, 095000-7560 |
| AP50901 | 8.1L | RE524368, RE501010, SE501940, 095000-0550 |
| AP50902 | 8.1L | RE524360, SE501935, 095000-5230 |
| AP50903 | 8.1L | RE524362, RE518725, SE501937, 095000-5160 |
| AP50904 | 8.1L | RE524369, RE504181, SE501941, 095000-0540 |
| AP50905 | 8.1L | RE524364, RE518723, SE501939, 095000-5190 |

9.0L John Deere HPCR

| | | |
|---------|------|---|
| AP51900 | 9.0L | RE546776, RE528407, RE529149, SE501947, 095000-6480 |
| AP51901 | 9.0L | RE543605, RE543352, SE502556, 095000-0610 |
| AP51902 | 9.0L | RE546777, RE528408, RE529151, SE501948, 095000-6471 |
| AP51903 | 9.0L | RE543606, RE543354, SE502557, 095000-0600 |

6.8L and 4.5L John Deere HPCR

| | | |
|---------|---------------|---|
| AP52900 | 6.8L and 4.5L | RE516540, RE519730, RE507860, SE501924, 095000-5050 |
| AP52901 | 6.8L and 4.5L | RE546781, RE524382, RE291118, SE501926, 095000-6490 |
| AP52902 | 6.8L and 4.5L | RE546784, RE531209, RE530362, SE501925, 095000-6310 |
| AP52903 | 6.8L and 4.5L | RE546783, RE531210, RE530361, SE501928, 095000-6320 |
| AP52904 | 6.8L and 4.5L | RE546780, RE533454, RE532216, SE501934, 095000-6880 |
| AP52905 | 6.8L | RE534111, RE533505, SE501933, 095000-7150 |
| AP52906 | 6.8L and 4.5L | RE546782, RE529414, RE529117, SE501927, 095000-6500 |
| AP52907 | 6.8L and 4.5L | RE545562, RE543351, SE502671, 095000-0590 |



Information is reference only. Call to verify part application.

ALSO AVAILABLE!

Installation information

Reinstallation of these injectors requires replacement of the one-time use components found in the table to the right.

Alliant Power's Injector Installation Kits will provide the necessary seals and hardware to reseal one injector.

Remanufactured High-Pressure Fuel Pumps



AP51950



AP52950



AP52951

Injector Installation Kits

| AP part number | Application | AP injectors |
|----------------|---------------|--|
| AP0120 | 8.1L | AP50900, AP50901, AP50902, AP50903, AP50904, AP50905 |
| AP0121 | 9.0L | AP51901, AP51903 |
| AP0122 | 9.0L | AP51900, AP51902 |
| AP0123 | 4.5L and 6.8L | AP52900, AP52901, AP52905, AP52906 |
| AP0124 | 4.5L and 6.8L | AP52907 |
| AP0125 | 4.5L and 6.8L | AP52902, AP52903 |
| AP0126 | 4.5L and 6.8L | AP52904 |

Remanufactured High-Pressure Fuel Pumps

| AP part number | Application | OEM cross reference | AP injectors |
|----------------|---------------|---------------------------------|---|
| AP51950 | 9.0L HPCR | RE571640, SE501922, 294050-0060 | AP51900, AP51902 |
| AP52950 | 4.5L and 6.8L | RE507959, SE501915, 294000-0050 | AP52900, AP52901, AP52902, AP52903, AP52904, AP52905, AP52906 |
| AP52951 | 4.5L and 6.8L | RE527528, SE501916, 294000-0560 | AP52901, AP52902, AP52903, AP52904, AP52906 |

Proudly Partnered With  ALLIANT POWER