



**ALLIANT  
POWER**  
**NAVISTAR®**  
**Pre-Programmed FICM**  
**2002-2009**

**The solution you need.  
The quality you trust.**

Alliant Power offers Remanufactured Fuel Injection Control Modules (FICMs) for Navistar applications.

- 12 part numbers offer complete application coverage
- Pre-programmed and calibrated to OEM specs
- Limits downtime
- Eliminates the trip to the dealer
- 24-month, unlimited mileage warranty

## Remanufactured Fuel Injection Control Module (FICM)

AP part number	ECM reference number	Year range	Application
AP65126	ANZKHA03	2004-2006	I6
AP65127	ANZKLA03	2004-2006	
AP65128	ANZNHA04	2004-2006	
AP65129	ANZNHB00	2004-2006	
AP65130	ANZNLA04	2004-2006	
AP65136	ANZKHB00	2004-2006	
AP65131	AQZ0AT04	2006-2009	V6
AP65132	AHZ7AI07	2002-2006	V8
AP65133	ANZ7BJ05	2002-2006	
AP65134	ANZ7BJ07	2002-2006	
AP65135	ANZ7BJ10	2002-2006	
AP65125	Non-Programmed	2004-2006	I6
	Non-Programmed	2002-2006	V8

Note: It is imperative to verify the ECM reference number prior to ordering. Choosing the wrong part could cause catastrophic engine failure. For proper ECM reference verification, refer to [APTB 01/20 R2](#) or call Technical Support at 800.735.9775.

### TECHNICAL TIP

### Pre-programmed Fuel Injection Control Module (FICM) for Navistar® Applications

Installing a pre-programmed FICM on an engine that does not have a current ECM calibration or matching reference number could cause catastrophic engine failure. If assistance is needed to verify ECM calibration status, please contact Technical Support at 800.735.9775.

When ordering a FICM, supplying the ECM reference number is required and can be located under the 'vehicle information' tab (image shown on right) in [ServiceMaxx™](#).

Specific ECM programming reference numbers can be found in the table below. Make sure the old FICM is plugged into the engine harness in order obtain the last 8 characters of the ECM reference number. If the ECM reference numbers is not displayed with the FICM plugged in, the FICM is damaged and will require a unprogrammed Alliant Power FICM AP65125.

For more information, refer to [NPA 01/20](#).

