

SUBJECT: Duramax L5D Exhaust Aftertreatment Product Identification




Fig. No.	Part Number	Description	Cross Ref	Year
1	AP63618	Exhaust Gas Temperature (EGT) Sensor Position #1	12672665, 12683486, 7502709C2	2017-2023
2	N/A	NOx Sensor	N/A	N/A
3	AP63617	Exhaust Gas Temperature (EGT) Sensor Position #2	12672666, 12683487, 7502710C2	2017-2023
4	AP63617	Exhaust Gas Temperature (EGT) Sensor EGT Position #3	12672666, 12683487, 7502710C2	2017-2023
5	N/A	DPF Differential Pressure Sensor	N/A	N/A
6	N/A	Hydrocarbon Injector	N/A	N/A
7	AP63617	Exhaust Gas Temperature (EGT) Sensor EGT Position #4	12672685, 12683525, 7502857C2	2017-2023
8	AP63615	Exhaust Gas Temperature (EGT) Sensor EGT Position #5	12672685, 12683525, 7502857C2	2017-2023
9	N/A	NOx Sensor	N/A	N/A